



ENGINEERING SAFETY CONSULTANTS

The Global Provider of Functional Safety Expertise and Technical Consultancy

Certificate of Conformity to IEC 61508 Safety Integrity Level (SIL) 2 in Terms of Random Hardware Performance Requirements

Functional Safety of Safety-Related Programmable Electronic Systems

The **Seagull Safety Ltd. SS76-TX CAT Transmitter** has been assessed and is considered capable for use in a low demand Safety Function up to SIL 2 with regard to random failure rate and architectural constraint. The assessment was based on the assumptions, data provided and recommendations given in:

- **Seagull Safety Ltd, SS76-TX CAT Transmitter, Hardware Safety Manual, SS55100-992, Issue 1.2, 14-Oct-15.**

The SS76-TX CAT Transmitter consists of the following modules:

- Transmitter Board – Part no. SS55100-301 Issue 3;
- Relay Board – Part no. SS55100-401 Issue 2.

The assessment was carried out against the following failure mode:

- Inability to read the pellistors impedance and give the correct 4-20mA analogue output signal within the specified tolerance.

The assessment was carried out to determine compliance with IEC 61508 with regards to:

- Random Hardware Failure with Predicted PFD <4.0 E-4 (assuming a 6 month proof test and a Mean Time to Repair of 8 hours);
- Architectural Constraint (Type B, SFF >90%, <99%).

Managing Director: Kenneth G L Simpson
Member of the IEC61508 committee

Assessment Date: October 2015, valid to October 2017

Certificate: C138_CT001 rev.1.docx



Reg:12Q12086

ENGINEERING SAFETY CONSULTANTS LTD

Collingham House

10-12 Gladstone Road Wimbledon London SW19 1QT UK

Telephone/Fax: +44 (0)20 8542 2807

E-Mail: info@esc.uk.net Web: www.esc.uk.net

Registered in England and Wales: 7006868

Registered Office: 10-12 Gladstone Road Wimbledon London SW19 1QT